

ARCHITECTS SQUARE Add.- 101, Vaarnika Kohli Colony, Behind Brew & Byte Restaurant, Thandi Sadak, Haldwani - 263 139, Distt, Nainital, Uttarakhand

Form-no-2

Mob.: 9412086006, 9997271777 e-mail: architectssguare@gmail.com

Ref .....

## Promise Certificate for Calamity Safety Requirement.

## TO WHOM IT MAY CONCERN..

Proposed Work – **Maharshi Vidya Mandir,Haldwani** Work of **Maharshi Vidya Mandir Trust.** Village/City- **Teen Taash,Manpur West,Dewalchaur,Rampur Road,Haldwani.Distt-Nainital.** Khet no-

HEIGHT OF BUILDING - 9.0MT.

1. Certify that the presented building map, building regulation shall be complete the contracted safety requirement and the information given by us is correct in our best knowledge and discretion.

2. It is also certified that on the basis of soil status with the calamity safety in the said building shall be made due specification to the nonstructural design and follows these provisions during the construction.

Name of the owner with date- 15.01.2021 Name- **Maharshi Vidya Mandir** Address - **Teen Taash,Manpur West,Dewalchaur,Rampur Road,Haldwani.Distt-Nainital.** 

Signature of Developer Date \_\_\_\_\_NA\_\_\_\_ Signature of Supervision Engineer Name- **NA** Address ......

Signature of Architect and Seal. Name- Sanjay Singh. Address- 101 Vaarnika,Kohli Garden Haldwani,Nainital-263139

Maharishi Vidya Mandir Teen Tas P.O. Manpur West HALDWANI-263139 (Nainital)



flyte Restaurant, Thandi Satas, r Disti Namital, Uttarakhand

Date

## CERTIFICATE OF STRUCTURAL STABILITY.

It is hereby certified that the structural and foundation designs of the Building at Maharishi Vidya Mandir School, Haldwani,Uttarakhand for which Map and Plans are submitted and sanctioned satisfy the safety requirements as stipulated in the relevant Indian Standard Codes,National Building Code guideline and documents specified in Annexure-1 Building Bye Laws.

Ar Sanjay K Singh. CA/96/19414

Ref



DATED- 15.02.2021

Maharishi Vidya Mandir Teen Tas P.O. Manpur West HALDWANI-263139 (Nainital)